

VEHICLE INSPECTION REPORT

YL21HLJ

DAF LF 180

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details

Reg. date	22/06/2021	VIN	XLRAEL1500L507186	Gearbox	AUTOMATIC
Year	2021	Body Style	Curtainside	Axle Combi	4x2
Mileage	413,162 Km Not Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	30/06/2026	Rear Doors	Barn
Colour	WHITE	Cab Type	DAY CAB	Tail Lift	Tuckaway

WARNING LIGHT ON DASH

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



