

VEHICLE INSPECTION REPORT

BL15YCE

Iveco Daily 70-170

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 06/07/2015

Year 2015

Mileage 108,452 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN ZCFC270C905012444

Body Style Panel Van

Service history Yes

Service documents Printout

MOT Due 31/03/2026

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

WARNING LIGHT ON DASH SIDE LOAD DOOR, AIR COMPRESSOR EQUIPMENT & 240V OUTLETS, WATER BOILER, CABLE FEEDER

Tyres

NSF NSI1

OSF OSI1

Spare NSO1

NSI2

OSI2

NSO2

OSO1

NSI3

OSI3

NSO3

OSO2

NSI4

OSI4

NSO4


OSO3

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Digital radio
- Passenger airbag
- Radio/CD
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Door osr
Dented
With Paint Damage



3: Qtr Panel osr
Dented
With Paint Damage

4: Dash Warning Lights
Displayed
No Action



5: Seat Base Cover osf
Torn
Over 3mm

6: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK		